HT730UHF

Software

What is the limitation about the developing version for SDK?

1. The library "unitechRFID.aar" needs DMService V1.2.8 or later version to support. You could get it in the Binary folder.
2. The Base Reader(HT730Reader, RP902Reader) should be initialized in non-main thread.
3. The application needs API version 28 or higher.
4. Android Studio 4.2.1 is recommended.