

URP1030

Tag

What is the proper reading distance from the URP1030?

The measurement distance should not exceed 1 meter.